ECS Configuration Change Request

ECS Configuratio		F	Page 1 of 1	Pages		
CCR No. 97-1436	Logged I	Date 10/9/97	Rev	Request T	ype CCR	
Priority Routine [Urgent	Emergency x	Affected Release	Ver. 2	Change Class	II
Title (description) GSFC Version 2 Hardwa	re/Network Diagram					
Documents Affected			Source Nos (RID, 1	NCR, Action It	em, GSFC CCR, e	tc.) or
151-TD-008-001			Tech Reference			ŕ
RTM Change	Start New Bas	eline X	•			
Problem						
Review and approve the Version 2 Hardware/Net will be used as a source of	work Diagram replace	es the former B0 diagra	m maintained by Randy	Haynes - Cha	ırleen Van Steenbei	rg, and
There are known discrep				· ·		vare
identifiers starting with still represents the most of discrepancy will be docu configuration will be characteristic.	current approved netw mented by CCR for C	ork configuration from CCB consideration. Up	n the old B0 baseline set on approval of each CC	. Upon the col R submitted, e	nclusion of the PCa either the as-built	
Proposed Solution Approve the above refere	enced document.					
Impact Analysis: Organizations Affected:	воо П	Contracts	ECS Chief Eng	FOS 🗔	M&O	<u></u>
Procurement	QO [X]	Rel. Dev	Rel. A	Rel. C	SCDO Arch.	X
Science Off	Security	Subcontrct	Sys. Eng	Sys Verf x		
Cost:	None x	Small	Medium	Large		
		(Not exceeding \$100,000)	(\$100,000 to \$500,000)	(Over \$500,000)		
Schedule:	None x	Other				
Additional LOC			Man-Month	ns		
Materials						
Originator Bob Hendry	/4128	Robert W. Hendry				
	<u> </u>	Signature			Date	
Office M&O	Office Manager	Tom Hickey				
<u> </u>	_	Signature			Date	
Disposition	Approved X	Approved w/Com	ment Forw	ard	Disapproved	
Comments:						
(CCB Chairperson	Terry Fisher				

CM01OC96 ECS

Date

Signature